


Number: QCSP 040002
 Order of the edition: A
 Date: 2004.03.01


Standard Gauge of Surface detect

[A] Diameter Gauge(mm)




※ Inner lines of white line indicate the regular length.

[B] Area Gauge (mm²)



※ From a through r of every group indicates an equal area.

[C] Line width & Length Gauge(mm)



※ Outer line of black circle indicate the regular diameter.
 Inner line of white circle indicate the regular diameter.

(Note)

- 1) Each gauge is to be used by comparing with the surface defect with the naked eyes.
- 2) Please cut out the (A). (B). (C) gauges from the dotted lines and use according to the needs.